A T H O S

Crèpe - Gasato/Gassed

Ne 28/2 - Nm 2/48000

COMPOSIZIONE

100% Cotone Pettinato

IMPIEGO

Tessitura ordito e trama

ATTENZIONI PARTICOLARI

Filato GASATO: dopo lavaggio, il colore può cambiare in conseguenza dell'eliminazione del tipico tono giallo dovuto alla gassatura.

Il filato melange gasato presenta generalmente una maggiore polverosità rispetto ai normali filati.

Le solidità sono riferite al prodotto dopo lavaggio.

I colori non sono solidi alla sovratintura ed al candeggio

MINIMI

Colori **STOCK SERVICE**: minimo una scatola

Maggiorazione prezzo applicata a quantità inferiori alla scatola

---

COMPOSITION

100% Combed Cotton

APPLICATION

Weaving warp and weft

SPECIAL CARES

GASSED yarn: KNIT after washing, the colour shade may change as a result of the elimination of the typical gassed yellow tone.

The gassed melange yarn generally presents more dust than normal yarns.

Fastness data refers to the product after washing.

Fastness of colours is not sufficient for overdyeing and bleaching

MINIMUM


STOCK SERVICE colours: one box minimum

For quantity less than one box: extra charge

INFORMAZIONI TECNICHE / TECHNICAL INFORMATIONS

SOLIDITÀ FASTNESS	ISO	SCARICO SU COTONE DISCHARGE ON COTTON	DEGRADO COLOR CHANGING
LAVAGGIO IN ACQUA 40° C WASHING AT 40° C	105-C06	4	4
LAVAGGIO A SECCO DRY CLEANING	105-D01	4	4
SUDORE ACIDO-ALCALINO ACID-ALKALINE PERSPIRATION	105-E04	4	4
SFREGAMENTO/RUBBING REATTIVI / ZOLFO A SECCO / DRY REATTIVI A UMIDO / WET ZOLFO A UMIDO / WET	105-X12	 3 - 4 3 - 4 2 - 3	 4 4 3
LUCE ARTIFICIALE ARTIFICIAL LIGHT	105-B02	-	4

Note: valori medi / average values



COTONIFICIO OLCESE FERRARI S.p.A.

Ufficio commerciale: Via Marzaghette, 7 - 25030 Adro (BS) ITALY

Tel. +39 030 7458830 - fax +39 030 7458833

sales.office@olceseferrari.it - www.olceseferrari.it

OEKO-TEX®
CONFIDENCE IN TEXTILES
STANDARD 100
1108631.0 CENTROCOT
Tested for harmful substances.
www.oeko-tex.com/standard100